## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.




FIGURE 1 (Prior Art)

2.

Ł

ARC (if necessary) + Photo resist.

- metal hardmark

Dielectric stack
(Can include dielectric hardweshs)


FIG. 2 PRIOR ART

FIG. 3 PRIOR ART

11110 11111

F1G. 4

PRIOR ART



şξ

The second of th

FIG. 6

61

Redeposition of metal hardmark

FIG. 7




FIG. 8